


EQUILIBRATOR™ Installation Single Tether



Extra Length of Tether

4. Connect to Well Cap
***This is the Depth Reference Point**

Well ID Tag

3. Attach Cable Tie thru Mesh & Ring at Nozzle end.

Stainless Steel Rings-Permanent

2. Attach Cable Tie thru Handle and Ring.

Pull tight & clip excess

Cable-Tie

1. Attach Weight to Ring on the end of the Tether. Allow Weight to rest on the bottom of the well

